• 4		Approved For Re	lease 2004/07/29		-00810A	002400640002	32
₩	er ad the	GLASSIFICA	ATION SECRET	* 25X1			
		CE	NTRAL INTELLIGE	NCE AGENC	~	REPORT	
		INFC	MOITAMR	REPO	AT	CD NO.	to a different
						25X1	1000
COUNTRY	* p.	Czechoslov	rakia			DATE DISTR. 7 Oct	20Der 1992
SUBJECT		Zdar Machi Strojirny	ne Shops and Fo	oundries (Z dar nad ⊃az	darske sevou	NO. OF PAGES	4
PLACE						NO. OF ENCLS.	
ACQUIRED DATE OF	25X1	4				SUPPLEMENT TO	25X1
INFO.						REPORT NO.	
		T		4			
					1		
			arthur manus are was a				- 1
ET OF THE UNITED 2	RAVARM MISS	econsation appetition for National State Heading of the Heading of the Heading Of The Heading of Tappets of Ta	en v matura evener 100	THIS I	S UNEVA	LUATED INFORMATION	M
		THOM OF THIS FORM IS PROMISE					
2.	The total first the come which	main raw material firm in Fible scrap, coasist as railreaded demonstration and delivered in the are three stone four-ton furnations. The 10-four-ton furnation of four a plant	iel is a poor sive (Ecoposition of old rei il cers. His iro res. It imports the USI 1,2 his butch reilroad andord electric urnace. The e ton furnaces us ce uses 505 to in Vir (050/NI	eras which Harodnipot ais, cant ai act a act ai act	commas i inik, Ji nd sheet sed in t and sil of accord yidenum ces used are manu watt-hour transfor	chortages in illowanthe mationality his very in irregular metal acraps, is the Edar factory lica, mainly from is not obtainable. It is not obtainable if in Edar: two 10-ifactured and delivers of electricity per ton. The material is no emergent in the in the energy in	red screp reddiverses. As the Car as the Car
32	iira Uwe	ers power to t n to the transf	he long-listons ormers for the	e circuit funsca; e	discom gaa ta	om the transformer sction (Fernledtur, ok for factory car	gstrenner, and s and tractors.
Ġ.	Engl well A re	ineer Malyser (t the charge mo scent total day to 65 percent o	ins) with sols no quickly. The r's cutout of the of the produced	state of overise method to material w	erheati produce maces ms defe		ior quality,
***	faci	tured by the ri 135, Vienna X, the machine sh	rm Wiener Brue The following to top (bulleting for	ckenbau und aquipment (*): Build	is fou	n of the stendard instruktions A.C., nd in the foundry	·meratian tagasas
on the second	n, bereigen Sin weg	Foresta le	erensi, constru	cted and de	livared.	In Janton-Plac	Kufaretes
	- 194 - 1	CLASSIFIC	CATION SECRET	TRIBUTION	e =		25X1

BEST COPY Available

strasse 70. Vienna V:

- (1) One 75-ton crane on 15 meter high longitudinal rails.
- (2) One 32-ton crane on 15 meter high longitudinal rails.
- One 32-ton crane on 15 meter high transverse rails,
- (4) One 32-ton grane on 8 meter high longitudinal rails; could be used as magnetic crane.
- (5) Eight 20-ton cranes on 8 meter high longitudinal rails.
- One five-ton crane on 8 meter high longitudinal rails.
- Two normal-gauge tracks which run transverse to the long axis of building #9. Low, man-powered cars are used for transportation on these tracks.
- One hydraulic press for reducing iron scrap to blocks, which are then transported to the furnaces.
- Two gas-powered drying ovens (Gastrockeneden) with a capacity of 100 cubic motors each.
- One water blast (Wassergeblasse-Wasserstrahlgeblasse) with compressor. This machine is of American origin.
- f. Three high pressure furnaces (Druckoefen), coal-powered, which are ready to be reconstructed for gas power.


Dullding #A

- Four small automatic lathes,
- One large vertical boring machine.
- Several small horizontal and vertical milling cutters (Fraesen).
- Several small boring machines.
- Three or four large vertical lathes (Karusselldrehbaenke).
- One large surface Jathe (Planscheibebank) with 400 mm diameter.4
- The Zdar foundry also produces the following semi-finished products: cog-wheels, cog-rails, small goar boxes, small foundation plates, wheels and exles. These products are cast in the foundry and shipped to other workshops for further treatment. The loading of these shipments takes place in building #9, where railroad cars are brought in at night and removed before the start of the 0600 shift.
- Both building #9 and building #4 are being developed. Central heating is being installed in these buildings as well as in the just completed administrative buildings. Next to building #9 is a bunker where casting forms will be stored; the bunker should be completed by the winter of 1953-1954. Another building is to be built on the southeast corner of the factory grounds to house the forge; it should be completed by 1956. Soveral temporary barracks have been erected in the northwest corner of the factory grounds to house various firms and support establishments participating in the construction of the Zdar plant.

25X1	Comment: Listed in the Jihlava telephone directory for 1951-52 as Kovosrot Ozerava, National Corporation, Jihlava Shop (Kovosrot Ostrava, Narodni
	podnik provosovna Jihlava).
25X1 <u> </u>	Comment: Prior to the recent Czesh currency reform, the price paid for one kilogram of vanadium was 380 crowns.
25X1	Comment: If the main transformer were damaged the entire foundry would be blacked out.
25X1	a shipment of machines, including
	two large surface lathes with a 400 rm and 200 mm diameter respectively and autolathes, is expected within two years. All machines deliveries come from the TOS (Tovarny obrabecien stroju, the nationalized machine production industry), in


kovice nad Labem, Zebrak pod Brdy, Hospivar u Prahy and Kurim (or Kourim). Approved For Release 2004/07/29 : CIA-RDP80-00810A002400640002-3

particular from the TOS in Varnadorf. Other factories of TOS are located in Cela-



- Fire Department
- Factory Militia First Aid Station
- 4. Machinery Hall #4
- 5. Employ
- 64 Kitchen
- 68 Messhall
- Hot Water Supply 7.
- Small Generator Dullding 83
- Foundry Hall #9 9..
- 10. Gas-Works, under construction
- II. Administrative Building
- Pattern Storage Area
- 13. Pattern Shop, under construction
- Hain Transformer 14.
- 15. Chimney
- 16. Storage Area
- 17. Administration Building for Hall #4
- 18. Grounds for future Smithy
- 19. Provisional Barracks
- 20. Transformer for Hall #4

SECRET



Transformer for One 10-ton Furnace **E**5 B6 Masonry for Furnaces

Transfermer for Four-ton and One 10-ton Furnace

B7, B8 Cas-heated Dry Oven

Two 10-ton Furnaces

Wire Drawing Shop

Four-ton Furnace

В

BI

B2

B3

B4

Pan Grinder (Kollergang) B9

- Foundry
- Storage Area for Round Steel Bars (Rauchschiff) Di Chill Chating - Eight Iron Molds
 - E Pattern Shop
 - Cleaners for Castings
 - G Storage Area for Finished Products
 - G1 Reserve Sand Storage Area
 - Н Storage Area for Defective Products
 - J Three High Compression Ovens
 - Normal Gauge Track